

Historic Property Survey Summary

County: **Forsyth**

SSN: **FY00634**

Blockface#:

Quad: Rural Hall
PIN:
X: 80.36199 **Y:** 36.15404
DOT Project #: R-2247
OSA#:

Update Mo: **11** Yr: **2006**

- No Alt Alt Det Rehab
 Removed Outbldg Loss
 No Acc. Not Fnd FileMsg
 Newly ID'd Needs Resch.

Property Name: **Evan Transou House**
 Street or 911 Address: **3255 Transou Rd East side**
 Location Description: **E side SR 3210, 0.05 mi N of SR 1525**
 Town/vicinity: **Pfafftown**
 District: **Pfafftown Historic District (DOE District) Contributing Building**
 District Dates: NRdate: SLdate: DOEdate: **1/2/1992**
 Local District:

Recommended for SL StudyList SLDate: NR NRDate: NR #
 DOE DOEDate: **1/2/1992**
 DOE Type: **ER** Local Status Local#: Ownership: **Private**

Principal Resource Material Integrity: **Medium** Condition: **Good** Location Integrity: **Original**

Architectural Data: Date: **ca. 1860** Major Style Group: **19th-20th c. trad/vern**
 Construction: **Log**
 Ext. Material: **Weatherboard:Plain** Later Covering: **Vinyl**
 Height: **2 story** Roof: **Side Gable** Plan: **Hall-parlor** Core Form (Domestic): **Single Pile**
 1st Design Source and attribution: **Unknown**

Major Theme 2nd Theme:
 Group Association: Religious Affiliation
 Historic Function: **Domestic - single dwelling**

Written Summary

Evan Transou, a wagon maker, built this house on the lot north of his brother's (Julius Transou) home. Interior features include flush board sheathing and a hand-carved newel post (Gwynne Taylor; Langdon Oppermann, Winston-Salem Northern Beltway report, 1991, p. 81).

This two-story, three-bay, side-gable-roofed, vinyl-sided log house has an early-twentieth-century hip-roofed front porch supported by Tuscan columns, replacement window sash, a four-panel front door, a rear shed additions, a one-story gabled ell, reconstructed brick end chimneys, and a metal roof. The wellhouse noted in earlier surveys is no longer extant (HF).

Outbuildings/Features

FeatureType	Material	CircaDate	Condition	Contrib
Smokehouse	Frame	1900	Good	

front-gable metal roof with overhang sheltering door; weatherboards and board-and-batten siding

Actions

Year	Month	Surveyor	Action/Report
1979	09	Taylor, Gwynne	Original County/Municipal Survey
1991	10	Oppermann, Langdon Edm	Survey for NCDOT report
2003	04	Woodard, Sarah, EPE	Survey for NCDOT report
2006	11	Fearnbach, Heather, EPE	Survey Update

