

**Historic Property Survey Summary**

County: **Forsyth**

SSN: **FY03221**

Blockface#:

**Quad:** Rural Hall  
**PIN:**  
**X:** 80.37012 **Y:** 36.16118  
**DOT Project #:**  
**OSA#:**

**Update** Mo: **01** Yr: **2008**

- No Alt  Alt  Det  Rehab  
 **Removed**  Outbldg Loss  
 No Acc.  Not Fnd  FileMsg  
 Newly ID'd  Needs Resch.

Property Name: **House**  
 Street or 911 Address: **5025 Skylark Rd North side**  
 Location Description:  
 Town/vicinity: **Pfafftown vicinity**  
 District: **None ()**  
 District Dates: NRdate: SLdate: DOEdat:

Recommended for SL  StudyList SLDate:  NR NRDate: NR #  
 DOE DOEDate:  
 DOE Type: Local Status Local#: Ownership: **Private**

**Principal Resource** Material Integrity: **High** Condition: **Good** Location Integrity: **Original**

**Architectural Data:** Date: **1937** Major Style Group: **Craftsman/Bungalow**  
 Construction: **Masonry Veneer**  
 Ext. Material: **Brick** Later Covering: **None**  
 Height: **1 1/2 story** Roof: **Cross Gable** Plan: **Not known** Core Form (Domestic): **N/A**  
 1st Design Source and attribution: **Unknown**

Major Theme 2nd Theme:  
 Group Association: Religious Affiliation  
 Historic Function: **Domestic - single dwelling**

**Written Summary**

Attempts to contact the current owner, Roger Jenkins, were unsuccessful. 1937 property tax card date.

This one-and-one-half-story, brick, cross-gable bungalow has an inset front porch supported by brick posts spanned by a pierced brick balustrade; Craftsman sash and casement windows; gabled bays on the east and west elevations; brick end and interior chimneys; and an enclosed rear porch. A frame shed stands northwest of the house; a frame garage is to the west (HF).

**Outbuildings/Features**

FeatureType	Material	CircaDate	Condition	Contrib
<b>Garage</b> hip-roofed garage with two open bays on east elevation, a sliding door on the south elevation, and a shed addition on the west elevation	Frame	1940	Good	
<b>Shed - general storage</b> front-gable, metal roof; concrete block stovepipe chimney; entrance on south elevation; vinyl siding	Frame	1940	Good	

**Actions**

Year	Month	Surveyor	Action/Report
2008	01	Fearnbach, Heather, EPE	Survey Update

